

Inconsistency in velocity



POSSIBLE CAUSE: Wrong matching between paintball and barrel.

SOLUTION: Use right size and quality paintball.



SOLUTION: Needs lubrication on striker and bolt.